

Release Note for VigorAP 910C

Firmware Version:	1.2.0.1
Release Type:	Normal
Release Date:	March 31, 2017
Applied Models:	VigorAP 910C

VigorAP 910C is a ceiling mount Access Point with PoE for offering power supply and support 300Mbps @2.4GHz, and 866Mbps @5GHz (11ac).

New Features

- None.

Improvement

- Corrected: Internet access problems occurred when VLAN tag and Isolate Member on SSID enabled.
- Corrected: In **Central AP Management >> APM Log**, data was removed by clicking Clear. However it was retrieved automatically if Refresh was clicked or access into the APM log page again.
- Corrected: Couldn't apply WLAN profile from Vigor router to VigorAP by AP Management.
- Corrected: Changed the URL link for FAQ/Application Note on web user interface.
- Improved: Display the device name of VigorAP on the WUI tab of browser.
- Corrected: While configuring Universal Repeater Parameters for WLAN (5GHz) through Quick Start Wizard, the channel and SSID were not changed according to the selected SSID and channel searched by AP Discovery.
- Corrected: The AP Discovery function could not run normally after clicking the Scan button for WLAN (2.4GHz).
- Improved: Data flow monitor can display total number of wireless clients.
- Corrected: Changed the word of MHZ into MHz.
- Corrected: Error occurred after changing the Channel Width in Wireless LAN (5G) >> Advanced Setting.
- Corrected: Isolate member feature did not work for some devices or circumstances.
- Corrected: Unable to input more than 15 characters as Device Name.
- Corrected: Running speed test on AP stopped local management or from the controller.
- Corrected: The font for the word, "Encrypt", in 2.4GHz Station List was different from

others.

- Corrected: Typo in **Central AP Management >> General Setup**.
- Improved: Some settings in **WLAN>>General Setup** are moved to **WLAN>>Advanced Setting**.

Known Issue

- Firmware version 1.2.0 may cause firmware upgrade failure while upgrading firmware from web user interface. When meeting firmware upgrade failure, please reboot VigorAP 910C and use Firmware Upgrade Utility to perform the firmware upgrade by a PC connected to LAN port of VigorAP 910C.

Notes

- None